Under Review Notification

Raised By: MYCHEL BEAUREGARD Product #: DART TOOLING TURBOMECA

Date: 19.02.15 Product Name: FUEL INJECTION PERMEABILITY TESTER

		"Y" or "N" Required for Each Part								
		Do not leave blank								
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
T-881698000	T-881698000 REV. 5	Υ	Υ	Ν	Υ	Υ	Ν	Ν	19-594	McMaster new spring clip is rotating when assemble
T-881698001	T-881698000 REV. 5	Υ	Υ	Ν	Υ	Υ	Ν	Ν	19-594	Need to add new hole to prevent spring clip rotation
T-881698009	T-881698000 REV. 5	Υ	Ν	Ν	Υ	N	Ν	Ν	19-594	Incorporate deviation to use McMaster spring clip
T-881696011	T-881698000 REV. 5	Υ	N	Ν	Υ	N	Ν	Ν	19-594	Need to change rivet in accordance with new spring cl
T-881696012	T-881698000 REV. 5	Υ	N	N	Υ	N	N	N	19-594	Need to change rivet in accordance with new spring cl

Description of Issue:

Deviation for use of McMaster hardware cause design intent failure

All stock must be quarantined

Drawing will be revised in priority and released quickly

Rework of parts are already done to fix design intent, drawing just need to be revised to accomplish final assembly steps

Distribution:

VP Operations

Director of Operations

Director Quality Assurance

QC Coordinator

Director of Engineering

Chief Engineer

Engineering Project Managers
Engineering Clerk

Customer Support Manager

Production Engineers Production Planners Purchasing Manager Technical Support

Product Manager - Solutions Provider Supply Chain Director / Senior Buyer

Marketing Eugene